


785000

785500

5303500

Rear layer:
Chľaba (30.03.2023)
 opacity 100%, without izolines



5303500

5303000

Legends:
 Positions of buoys are from ENC

- Red buoy
- Luminous red buoy
- Green buoy
- Luminous green buoy
- Fairway
- Isoline 2,5m below LNWL
- River km mark
- Hektometer
- Border of measurement

© Ortofotomozaika SR, GKÚ Bratislava, NLC, ESRI, Erosense, Geodis, GeoEye, USGS

© Bathymetry plan: Hydromorphology department, Radovan Terek

785000 5303000

785500

SLOVENSKÝ
 VODOHOSPODÁRSKY
 PODNIK, štátny podnik
 Povodie Dunaja, odštepny závod


Karľovská 2, 842 17 Bratislava
 tel.č.: 02/60 292 494
 email: Hydromorfologia_BA@svp.sk

Critical sections of the Danube River

Chľaba

sheet: DIN-A3
 rkm: 1711.5 - 1710.7
 priority: 2
 page: 23/23

date of measurement : 19.09.2023	gauge value : Štúrovo 82 cm	elevation system/ reduced level: LNWL2022
date of processing : 25.09.2023	discharge : Štúrovo Q= 1400 m ³	coordinate system: UTM 33N



100 0 100 200 m

1:3 000
 MultiBeam

depth below:
LNWL2022

DEM