



785000

785500

5303500

 Rear layer:
Chľaba (7.2024)
 opacity 100%, without izolines










17
11



5303500

5303000

Legends:
 Positions of buoys are from ENC


-  - Red buoy
-  - Luminous red buoy
-  - Green buoy
-  - Luminous green buoy
-  - Fairway
-  - Isoline 2,5m below LNWL
-  - River km mark
-  - Hektometer
-  - Border of measurement

© Ortofotomozaika SR; „GKÚ Bratislava, NLC“, ESRI, Erosense, Geodis, GeoEye, USGS

© Bathymetry plan: Hydromorphology department, Radovan Terek

785000 5303000

785500


 SLOVENSKÝ
 VODOHOSPODÁRSKY
 PODNIK, štátny podnik
 Povodie Dunaja, odštepny závod

Martinská 49, 821 05 Bratislava
 tel.č.: 02/60 292 494
 email: Hydromorfologia_BA@svp.sk

Critical sections of the Danube River
Chľaba

date of measurement : 03.12.2024 gauge value : Štúrovo 115 cm elevation system/ reduced level: LNWL2022
 date of processing : 16.12.2024 discharge : Štúrovo Q=1595m³ coordinate system: UTM 33N

sheet: DIN-A3
 rkm: 1711.5 - 1710.7
 page: 23/23



100 0 100 200 m

1:3 000
MultiBeam

depth below:
 LNWL2022

DEM

